

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

DS585
NW
1/2-1
0.883 mi.
4661 ft.

PARK CONSTRUCTION
BAY 44TH ST AND SHORE PKWY
BROOKLYN, NY

NY Spills **S110750922**
N/A

Site 2 of 3 in cluster DS

Relative:
Higher

Actual:
9 ft.

SPILLS:

Name: PARK CONSTRUCTION
Address: BAY 44TH ST AND SHORE PKWY
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1009613 / 2010-12-20
Facility ID: 1009613
Facility Type: ER
DER Facility ID: 398127
Site ID: 443173
DEC Region: 2
Spill Cause: Traffic Accident
Spill Class: C4
SWIS: 2401
Spill Date: 2010-12-09
Investigator: RVKETANI
Referred To: Not reported
Reported to Dept: 2010-12-09
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial Vehicle
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported

Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2010-12-09
Spill Record Last Update: 2010-12-21
Spiller Name: MIKE CIAVATTA
Spiller Company: WILLIAM A GROSS CONSTRUCTION
Spiller Address: Not reported
Spiller Company: 999
Contact Name: MIKE CIAVATTA
DEC Memo: "12/9/10 - Raphael Ketani. I spoke to Mike Ciavata of William A. Gross Construction (516) 250-4093. He said that a truck was delivering soil when it flipped onto its side and about 30 gals. of diesel fuel spilled out. He said that he had backhoe digging up the contaminated soil right now. The soil was being placed on 3 MIL thick plastic sheeting and will be covered once it's all dug up. He said that the soil will got to Clean Earth in Carteret, NJ. I asked Mr. Ciavata to send the DEC the disposal manifests and some pictures of the cleanup. He said that he will. 12/20/10 - Raphael Ketani. Damien Ricci of William A. Gross Construction sent me the pictures and manifest showing that the spill had been cleaned up. As the soil was collected soon after the spill took place and was confined to a small area of a small construction site, I determined that the spill was not a threat to the public or the environment. Therefore, I closed the spill case."

Remarks: "Caller advised tractor trailer tipped over and spilled 30 gallons of diesel onto soil. Clean up is in process."

All Materials:
Site ID:

443173

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Operable Unit ID: 1193646
Operable Unit: 01
Material ID: 2189108
Material Code: 0008
Material Name: diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: 30.00
Units: G
Recovered: 30.00
Oxygenate: Not reported